














# EXISTING CONDITIONS ANALYSIS

-  Major vehicular entry points to corridor
-  Railroad crossings
-  Signalized intersection
-  Stop sign at intersection
-  School crossing
-  Pedestrian sidewalk
-  Major vehicular traffic route
-  Minor vehicular traffic route
- 
- 
- 
- 





# EXISTING CONDITIONS ANALYSIS

 Major vehicular entry points to corridor

 Railroad crossings

 Signalized intersection

 Stop sign at intersection

 School crossing

 Pedestrian sidewalk

 Major vehicular traffic route


 Minor vehicular traffic route













# EXISTING CONDITIONS ANALYSIS

 Major vehicular entry points to corridor

 Railroad crossings

 Signalized intersection

 Stop sign at intersection

 School crossing

 Pedestrian sidewalk

 Major vehicular traffic route


 Minor vehicular traffic route

 Railroad line

 Cobble wall

 Margaret Avenue

 Study boundary















MARGARET AVENUE CORRIDOR STUDY

TERRE HAUTE

A LEVEL ABOVE



# EXISTING CONDITIONS ANALYSIS

-  Major vehicular entry points to corridor
-  Railroad crossings
-  Signalized intersection
-  Stop sign at intersection
-  School crossing
-  Pedestrian sidewalk
-  Major vehicular traffic route
-  Minor vehicular traffic route
-  Railroad line
-  Cobble wall
-  Margaret Avenue corridor
-  Corridor study limits

